

Recommended Software Update for MicroVision EX

Pulsafeeder is always working to improve Pulsalink communications. Having the latest software installed on your MicroVision EX takes full advantage of the latest performance enhancements over your current software version. To eliminate any Pulsalink connectivity issues, Pulsafeeder **strongly** recommends downloading and installing version **R0028 (2.8)** on your MVEX.

Contact the Pulsafeeder technical department ppgspotech@idexcorp.com with the model number of your controller that needs updating. We will send you the **R0028 (2.8)** files. There is a “how to” MicroVision EX Software Update Tech Bulletin on the www.pulsatron.com website.

NOTE: Remember to download any Data Log information before updating the software because it will be erased.

*NOTE: If you have a MVEX controller made after **April 2018**, you will have software version **C0005 (3.0)** installed and you do not need a software update.*